



Briefing
for
Mariner's

| | | | |
|-----------------|------------|------------|-----|
| Date of Notice: | 08/08/2017 | Notice No. | 315 |
|-----------------|------------|------------|-----|

This briefing is intended to update mariners on marine operations for the Block Island Wind Farm.

For general information on the Block Island Wind Farm, please visit: www.dwwind.com

If you have any questions on the offshore activities, or request further information, please contact:

John O’Keeffe at jokeeffe@dwwind.com or 401-868-4228.

For all fishing related inquiries, please contact:

Elizabeth Marchetti at rifisheryliaison@gmail.com or 401-954-2902.

| Vessel Name | Site Function | Week Of August 8 2017 | Outlook |
|--|----------------------|--|--|
| F/V Lyndsey E | Support vessel | Transiting between Block Island & BIWF for visual inspections and public relations trips | Transiting between Block Island & BIWF for visual inspections and public relations trips |
| CTV Atlantic Pioneer | Crew Transfer Vessel | Transiting between Quonset, Block Island and Block Island Wind Farm turbines #1-5 / technicians transfer to foundations for operations & maintenance | Transiting between Quonset, Block Island and Block Island Wind Farm turbines #1-5 / technicians transfer to foundations for operations & maintenance |
| RV Shearwater | Research Vessel | Vessel will conduct brief underwater verification of cable protection along BIWF Export cable route from Block Island out to BIWF | !-2 days of cable protection verification |
| | | | |
| | | | |
| Operations & Maintenance activities continue at the BIWF | | **PLEASE NOTE THAT NO VESSELS SHOULD BLOCK ACCESS TO THE CREW TRANSFER VESSEL LADDER ACCESS** | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

All mariners transiting or fishing in the area of the wind farm are requested to provide a wide berth to support vessels. Vessels transiting in the vicinity of the BIWF should operate at a no wake speed in a manner that will not endanger support

vessels or associated equipment. Mariners are requested to remain clear of all work platforms and attendant vessels during BIWF operations and otherwise use extreme caution when navigating in the vicinity of the BIWF.

Block Island Wind Farm – Coordinates & Installation Status

| ID | Latitude | Longitude | Status |
|-------------------------|--------------|---------------|-----------------------------------|
| BIWF 1 | 41° 7.546' N | 71° 30.451' W | Foundation and turbine installed. |
| BIWF 2 | 41° 7.193' N | 71° 30.837' W | Foundation and turbine installed. |
| BIWF 3 | 41° 6.883' N | 71° 31.270' W | Foundation and turbine installed. |
| BIWF 4 | 41° 6.609' N | 71° 31.744' W | Foundation and turbine installed. |
| BIWF 5 | 41° 6.380' N | 71° 32.258' W | Foundation and turbine installed. |
| Submarine Cable (Green) | | | Submarine cable installed |

**not to be used
for navigation

